

Date Completed: \_\_\_\_\_ Failure Code: \_\_\_\_\_

Completed By : \_\_\_\_\_ Signature : \_\_\_\_\_

Accepted By : \_\_\_\_\_ Signature : \_\_\_\_\_

**\*\* Delay Codes Legend \*\***

W=Whse    C=CrSp    T=Tag    TL=Tool    P=Plan  
 \*\* Record Time Daily \*\*                      Delays

Step	Job Scope	MN	DY	Safety and Additional Information
------	-----------	----	----	-----------------------------------

Emp No	Date	Hours	Code/Hrs
--------	------	-------	----------

1 REPAIR AND RETURN, BOARD, FOXBORO, G0113CH,  
TRANSFER SWITCH ASSEMBLY, POWER MONITOR  
BOARD, TRANSFER SWITCH ASSEMBLY FOXBORO  
P/N-G0113CH. IPSC S/N-68705

1 1

STK NO: 68705  
QTY: 1  
ORIG WO: 02-60456-65  
STK ISSUE: 279636

ITEM DESCRIPTION:  
BOARD, FOXBORO, G0113CH, TRANSFER SW.,  
ASSEMBLY.  
POWER MONITOR BOARD TRANSFER SWITCH  
ASSEMBLY.  
FOXBORO, P/N G0113CH

**\*\* IMPORTANT NOTICE \*\***

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



**IP7\_037490**

CREW: 89

WORK ORDER TYPE: REBUILDS

02-60456-77

ISSUE DATE 01/06/11

Page 2 Of 2

\*\* Work Order Parts List \*\*

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
-----	-----	-----	-----	---	-----	-----	-----
1 DIRECT	REPAIR & RETURN: BOARD, POWER MONITOR, TRANSFER SWITCH ASSEM	04-39739	05/15/04	EA	1	0	1

IP7\_037491